



6/6

FIG. 6

(a)




(b)




(FORMATION OF COLUMN AND WALL MEMBERS BY PATTERNING)

(c)




(APPLYING OF SEAL MEMBER)

(d)



(ASSEMBLING)

(e)



(INJECTION OF LIQUID CRYSTAL)